

Message

From: Tinger, John [/O=EXCHANGELABS/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=B6B7405A2BA548B5886C18A0A64675CC-JTINGER]
Sent: 12/3/2021 12:21:13 AM
To: Bill Boswell [bboswell@kohanaiki.com]
CC: alec.wong@doh.hawaii.gov; Kurano, Matthew [matthew.kurano@doh.hawaii.gov]; Damien Souza [dsouza@kohanaiki.com]
Subject: Kohanaiki wastewater treatment system inspection report - Transmittal
Attachments: 2021-11-21 Kohanaiki NPDES Compliance Inspection Report and Transmittal.pdf

Bill,

Please find attached Inspection Report and Cover Letter for wastewater treatment facility inspection conducted November 21, 2021 for the Kohanaiki Community Association located in Kailua Kona. A hard copy will be sent to your attention.

As described in cover letter, please note that the inspection focused solely on assessing the validity of a complaint. While inspectors did not observe treated wastewater directly being discharged to surface waters, the inspection does not attempt to evaluate, and makes no conclusions, regarding any potential subsurface pathways of treated wastewater reuse to surface waters. The evaluation of subsurface pathways is much beyond the scope of this site inspection; apologies if the report was unclear that this assessment was not conducted.

Please feel free to contact me if you have any questions,

Best,

John Tinger

US EPA | Wastewater Enforcement
75 Hawthorne St (ENF 3-1) | San Francisco CA 94105
(415) 972-3518 | Cell (415) 420-2217